



USED IF:

- if plate has capped-off threaded standoff on front of engine, plate is normally ribbed also drive is female slotted drive
- then the engine requires:

- (1) 32608 BC-3110 Drive Joint .500
Normally sent Reverse Rotation
Direct Rotation Shown
- (1) 37626 821874 Drive Pin *Special w/shoulder*

PERKINS ADAPTER

SCALE: FULL | DATE: 4/12/88 | PART # 06062



GLENDINNING MARINE

RT.5 BOX 188 CONWAY SC 29526